



Start with an empty, sturdy pallet. Please make sure that no nails, splinters or sharp edges exist.

View this Guide Online: <http://www.csileasingservices.com/info/>



To add to the overall strength of the final pallet, add on a piece of cardboard or like material to the base.

View this Guide Online: <http://www.csileasingservices.com/info/>



After packing printers in boxes, either with bubble wrap or foam, place the printers on the pallet.

View this Guide Online: <http://www.csileasingservices.com/info/>



Make sure that each of the boxes is placed within the border of the pallet to reduce chance of damage.

View this Guide Online: <http://www.csileasingservices.com/info/>



Stack the printers vertically as high as three layers if need be. Remember, safety first.

View this Guide Online: <http://www.csileasingservices.com/info/>



Remember when wrapping with plastic wrap to start from the base of the pallet to improve stability.

View this Guide Online: <http://www.csileasingservices.com/info/>



Remember when wrapping with plastic wrap to start from the base of the pallet to improve stability.

View this Guide Online: <http://www.csileasingservices.com/info/>



The pallet shown here has both printers and duplex units (smaller boxes) wrapped and is ready to ship.

View this Guide Online: <http://www.csileasingservices.com/info/>