



Start with your flat panel on a sturdy flat surface.
Be sure to secure all cords attached to unit.

View this Guide Online: <http://www.csileasingservices.com/info/>



Line an empty box with two lines of bubblewrap - which will create extra protection where the two cross.

View this Guide Online: <http://www.csileasingservices.com/info/>



Place an extra layer of folded bubblewrap into the bottom of the box to help protect the flat panel.

View this Guide Online: <http://www.csileasingservices.com/info/>



Place the unit face-down onto a sheet of bubble wrap. Please remember to secure all included cords.

View this Guide Online: <http://www.csileasingservices.com/info/>



Carefully roll the flat panel into the bubblewrap - make sure that you are keeping all edges of the unit covered.

View this Guide Online: <http://www.csileasingservices.com/info/>



After you've completed wrapping, add a strip of tape to connect the end of the bubblewrap roll to itself.

View this Guide Online: <http://www.csileasingservices.com/info/>



Gently place the flat panel face up into the box.
Remember to make sure that all edges are protected.

View this Guide Online: <http://www.csileasingservices.com/info/>



In a standard box like this one, up to three flat panel monitors can be shipped together.

View this Guide Online: <http://www.csileasingservices.com/info/>



Fold in the remaining bubblewrap over the flat panels that are inside the box for additional protection.

View this Guide Online: <http://www.csileasingservices.com/info/>



Close the four sides of the box - make sure that all packing material is out of harms way.

View this Guide Online: <http://www.csileasingservices.com/info/>



Secure the box with tape.

View this Guide Online: <http://www.csleasingservices.com/info/>